



WEAR

# VOLVO TRACTOR 26446 (S/N 4V4MC9EG3HN985335)


Differential Fluid NOT GIVEN (--- GAL)

# COMPONENT CONDITION SUMMARY





## Non-ferrous Metals



## RECOMMENDATION

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

## PROBLEMATIC TEST RESULTS

Sample Status				SEVERE				
Iron	ppm	ASTM D5185m	>500	🛑 1523				
Chromium	ppm	ASTM D5185m	>10	<b>1</b> 4				
Nickel	ppm	ASTM D5185m	>10	<b>1</b> 1				
Lead	ppm	ASTM D5185m	>25	<b>4</b> 0				
Copper	ppm	ASTM D5185m	>100	<u> </u>				
Tin	ppm	ASTM D5185m	>10	<b>5</b>				
Water	%	ASTM D6304	>.2	<b>6</b> 0.580				
ppm Water	ppm	ASTM D6304	>2000	<b>6800</b>				

Customer Id: PERDILSC Sample No.: PCA0102799 Lab Number: 05939381 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.		
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Water Access			?	We advise that you check for the source of water entry.		

# HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

Sample Rating Trend

WEAR

X

#### Machine Id VOLVO TRACTOR 26446 (S/N 4V4MC9EG3HN985335) Component Differential

Fluid NOT GIVEN (--- GAL)

### DIAGNOSIS

#### Recommendation

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

#### 🛡 Wear

Gear wear is indicated. Bearing and/or bushing wear is indicated.

#### Contamination

There is a moderate concentration of water present in the oil.


#### Fluid Condition

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0102799		
Sample Date		Client Info		23 Aug 2023		
Machine Age	hrs	Client Info		183043		
Oil Age	hrs	Client Info		183043		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS	6	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	<b>1</b> 523		
Chromium	ppm	ASTM D5185m	>10	<b>1</b> 4		
Nickel	ppm	ASTM D5185m	>10	<b>1</b> 1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	8		
Lead	ppm	ASTM D5185m	>25	<b>4</b> 0		
Copper	ppm	ASTM D5185m	>100	<u> </u>		
Tin	ppm	ASTM D5185m	>10	▲ 5		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		154		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		28		
Magnesium	ppm	ASTM D5185m		10		
Calcium	ppm	ASTM D5185m		36		
Phosphorus	ppm	ASTM D5185m		1479		
Zinc	ppm	ASTM D5185m		86		
Sulfur	ppm	ASTM D5185m		29005		
CONTAMINAN	ſS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	56		
Sodium	ppm	ASTM D5185m	210	11		
Potassium	ppm	ASTM D5185m	>20	6		
Water	%	ASTM D6304		▲ 0.580		
ppm Water	ppm	ASTM D6304		▲ 5800		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
	scalar	*Visual	NONE	NONE		
Yellow Metal		*Visual	NONE	NONE		
	scalar					
Precipitate	scalar scalar		NONE	NONE		
Precipitate Silt	scalar	*Visual	NONE	NONE NONE		
Precipitate Silt Debris	scalar scalar	*Visual *Visual	NONE	NONE		
Precipitate Silt Debris Sand/Dirt	scalar scalar scalar	*Visual *Visual *Visual	NONE NONE	NONE NONE		
Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NORML	NONE NONE NORML		
Precipitate Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NORML NORML	NONE NONE NORML NORML		
Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NORML	NONE NONE NORML		



# **OIL ANALYSIS REPORT**



Submitted By: KEVIN HOOKS

Page 4 of 4

US 29536

no image