


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id **426143**

Component

2 Differential

GEAR OIL SAE 80W90 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. (Customer Sample Comment: 2nd Axle / Tag)

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

				Aug2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0089468		
Sample Date		Client Info		25 Aug 2023		
Machine Age	mls	Client Info		445086		
Oil Age	mls	Client Info		445086		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
WEAR METAL	_S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>500	438		
Chromium	ppm	ASTM D5185m	>10	4		
Nickel	ppm	ASTM D5185m	>10	10		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	4		
_ead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m		1		
Борро. Гin	ppm	ASTM D5185m	>100	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	41		
Barium	ppm	ASTM D5185m	200	0		
Molybdenum	ppm	ASTM D5185m	12	1		
Manganese	ppm	ASTM D5185m		6		
Vagnesium	ppm	ASTM D5185m	12	6		
Calcium	ppm	ASTM D5185m	150	155		
Phosphorus	ppm	ASTM D5185m	1650	484		
Zinc	ppm	ASTM D5185m	125	41		
Sulfur	ppm	ASTM D5185m	22500	20514		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	48		
Sodium	ppm	ASTM D5185m	>170	0		
Potassium	ppm	ASTM D5185m		4		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Free Water	scalar	*Visual	Z.L	NEG		
FLUID PROPE		method	limit/base		historya	hictory
TLUID PHOPE		memou	- minibase	current	history1	history2





OIL ANALYSIS REPORT



SAMP	LE IMAGES	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

GRAPHS









Laboratory Sample No. Lab Number

: 05940411 Unique Number : 10631023 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0089468 Received Diagnosed

: 31 Aug 2023 : 05 Sep 2023 Diagnostician : Don Baldridge GFL Environmental - 983 - Sugar Land Hauling 16011 West Belfort Street

Sugar Land, TX US 77498

Contact: TECHNICIAN ACCOUNT

wcgfldemo@gmail.com T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: