

PROBLEM SUMMARY

Grinding Room Machine Id main plant hydraulics

Component Hydraulic System Fluid MOBIL DTE 25 (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	MARGINAL	ABNORMAL		
Iron	ppm	ASTM D5185m	>20	<u> </u>	A 35	4 35		
Copper	ppm	ASTM D5185m	>20	<u> </u>	1 16	1 09		

Customer Id: KRANEW Sample No.: PCA0099616 Lab Number: 05948995 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 <u>don.b505@comcast.net</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

30 May 2023 Diag: Doug Bogart



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. The iron level is abnormal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

15 May 2023 Diag: Don Baldridge

21 Mar 2023 Diag: Doug Bogart



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. The iron level is abnormal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



view repor



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. The iron level is abnormal. The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend

WEAR

Grinding Room Machine Id main plant hydraulics

Component Hydraulic System Fluid MOBIL DTE 25 (--- GAL)

DIAGNOSIS

A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

🔺 Wear

The copper level is abnormal. The iron level is abnormal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

						•
		Jg2022 Feb2	2023 Feb2023 Feb202	3 Mar2023 Mar2023 Mar20	123 Sep202	
SAMPLE INFORM	NATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0099616	PCA0092061	PCA0092056
Sample Date		Client Info		05 Sep 2023	30 May 2023	15 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	MARGINAL	ABNORMAL
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<mark>/</mark> 35	A 35	4 35
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	<1
Titanium	ppm	ASTM D5185m		<1	<1	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	1	2
Lead	ppm	ASTM D5185m	>20	<1	0	0
Copper	ppm	ASTM D5185m	>20	<u> </u>	1 16	<u> </u>
Tin	ppm	ASTM D5185m	>20	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		1	2	2
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		0	0	3
Calcium	ppm	ASTM D5185m		70	77	74
Phosphorus	ppm	ASTM D5185m		391	396	409
Zinc	ppm	ASTM D5185m		455	468	499
Sulfur	ppm	ASTM D5185m		1439	1486	1642
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1	<1	<1
Sodium	ppm	ASTM D5185m		3	2	3
Potassium	ppm	ASTM D5185m	>20	17	21	21
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	375	174	654
Particles >6µm		ASTM D7647	>2500	58	61	140
Particles >14µm		ASTM D7647	>640	3	10	12
Particles >21µm		ASTM D7647	>160	1	4	3
Particles >38µm		ASTM D7647	>40	0	0	1
Particles >71µm		ASTM D7647	>10	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/16	16/13/9	15/13/10	17/14/11
Oil Cleanliness	ATION	ISO 4406 (c) method	>20/18/16 limit/base	16/13/9 current	15/13/10 history1	17/14/11 history2



OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	LIGHT	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	44.2	45.6	45.1	45.3
SAMPLE IMAGES		method	limit/base	current	history1	history2

Color



Bottom



To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Certificate L2367

Submitted By: RYAN SCHMID

Contact: RYAN SCHMID

T: (507)568-0338

F: (507)354-7927

ryan.schmid@kraftheinz.com