

OIL ANALYSIS REPORT

KEMP QUARRIES / RIVER VALLEY ARKOMA

Sample Rating Trend



DIAGNOSIS

Recommendation

Contamination


Fluid Condition

Wear

oil


service.


WL108 Component Front Left Final Drive MOBIL MOBILTRANS HD 50 (--- GAL)





OIL ANALYSIS REPORT





Certificate L2367