

OIL ANALYSIS REPORT

Sample Rating Trend


NORMAL



KEMP QUARRIES / RIVER VALLEY BACKBONE WL088

Component Front Differential

MOBIL MOBILTRANS HD 50 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.


#Z015 Nov2015 Jun2016 May2017 Aug2018 Apy2019 Aug2019 May2021 Jun2022 Aug2023						
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0084901	PCA0085866	PCA007023
Sample Date		Client Info		02 Oct 2023	09 Aug 2023	14 Nov 2022
Machine Age	hrs	Client Info		36443	36443	5802
Oil Age	hrs	Client Info		600	30641	5802
Oil Changed		Client Info		Not Changd	Not Changd	Changed
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	31	26	91
Chromium	ppm	ASTM D5185m	>3	0	0	<1
Nickel	ppm	ASTM D5185m	>3	<1	0	0
Titanium	ppm	ASTM D5185m	>2	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>30	0	4	4
Lead	ppm	ASTM D5185m	>13	<1	<1	<1
Copper	ppm	ASTM D5185m	>103	3	2	10
Tin	ppm	ASTM D5185m	>5	<1	0	<1
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		1	0	8
Barium	ppm	ASTM D5185m		1	0	0
Molybdenum	ppm	ASTM D5185m		<1	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		11	12	8
Calcium	ppm	ASTM D5185m		2787	2944	2882
Phosphorus	ppm	ASTM D5185m		1014	1032	1033
Zinc	ppm	ASTM D5185m		1234	1247	1262
Sulfur	ppm	ASTM D5185m		5046	4967	6008
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>100	31	29	46
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	2	1	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG



OIL ANALYSIS REPORT









Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : MOB 1

: PCA0084901 : 05976647 : 10688597

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 11 Oct 2023 : 12 Oct 2023 : Wes Davis Diagnostician

Kemp Quarries - River Valley - Backbone

5600 S Hwy 253 Huntington, AR US 72940

Contact:

F:

backbone@rivervalleyquarries.com T:

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)