


PROBLEM SUMMARY

Area [968542330] Machine Id KR-GR-000293 - MARLEN VAC PUMP (S/N STUFF A - 11513100) Component

Hydraulic System

HYDRAULIC OIL FG ISO 100 (60 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS						
Sample Status			ABNORMAL	NORMAL	ABNORMAL	
Particles >4µm	ASTM D7647	>10000	<u> </u>			
Particles >6µm	ASTM D7647	>2500	<u> </u>			
Oil Cleanliness	ISO 4406 (c)	>20/18/16	<u> </u>			


Customer Id: KRAKIR Sample No.: PCA0106045 Lab Number: 05979589 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component if applicable.		

HISTORICAL DIAGNOSIS

21 Jul 2023 Diag: Jonathan Hester



 \checkmark

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report

18 Apr 2023 Diag: Don Baldridge

VISUAL METAL



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.Moderate concentration of visible metal present. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

VIS DEBRIS





18 Jan 2023 Diag: Don Baldridge

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.



OIL ANALYSIS REPORT

Area [968542330] Machine Id KR-GR-000293 - MARLEN VAC PUMP (S/N STUFF A - 11513100) Component

Hydraulic System

HYDRAULIC OIL FG ISO 100 (60 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0106045	PCA0102538	PCA0093099
Sample Date		Client Info		15 Oct 2023	21 Jul 2023	18 Apr 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	ABNORMAL
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0	<1	0
Chromium	ppm	ASTM D5185m	>20	0	1	0
Nickel	ppm	ASTM D5185m	>20	0	1	0
Titanium	ppm	ASTM D5185m		0	1	0
Silver	ppm	ASTM D5185m		0	3	0
Aluminum	ppm	ASTM D5185m	>20	<1	0	0
Lead	ppm	ASTM D5185m	>20	0	8	0
Copper	ppm	ASTM D5185m		3	2	<1
Tin	ppm	ASTM D5185m	>20	0	2	0
Vanadium	ppm	ASTM D5185m		0	2	0
Cadmium	ppm	ASTM D5185m		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	<1	0
Barium	ppm	ASTM D5185m	5	0	0	0
Molybdenum	ppm	ASTM D5185m	5	0	<1	0
Manganese	ppm	ASTM D5185m	_	<1	<1	0
Magnesium	ppm	ASTM D5185m	5	0	19	<1
Calcium	ppm	ASTM D5185m	12	0	0	0
Phosphorus	ppm	ASTM D5185m	400	267	57	8
Zinc	ppm	ASTM D5185m	12	0	0	0
Sulfur	ppm	ASTM D5185m	650	779	255	34
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	6	3	3
Sodium	ppm	ASTM D5185m		<1	43	0
Potassium	ppm	ASTM D5185m	>20	0	100	1
FLUID CLEAN	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	19203		
Particles >6µm		ASTM D7647	>2500	<u> </u>		
Particles >14µm		ASTM D7647	>640	445		
Particles >21µm		ASTM D7647	>160	109		
Particles >38µm		ASTM D7647	>40	9		
Particles >71µm		ASTM D7647	>10	2		
Oil Cleanliness		ISO 4406 (c)	>20/18/16	A 21/20/16		
FLUID DEGRA		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.50	0.072	0.065	
			0.00	01012	0.000	





LE

OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	🔺 MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	NONE	A MODER
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	100	100	105	105
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color						





Bottom





Certificate L2367

Contact/Location: WALLACE WARD - KRAKIR