


# **PROBLEM SUMMARY**


# Walgreens - Tractor [Walgreens - Tractor] 136A624119


Diesel Engine


PETRO CANADA DURON SHP 10W30 (11 GAL)



### **COMPONENT CONDITION SUMMARY**







### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

### PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	 
Silicon	ppm	ASTM D5185m	>25	<b>41</b>	 

Customer Id: TSV1365 Sample No.: PCA0103696 Lab Number: 05980314 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMEND	RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

# HISTORICAL DIAGNOSIS




# **OIL ANALYSIS REPORT**

# Walgreens - Tractor [Walgreens - Tractor] 136A624119

**Diesel Engine** 

PETRO CANADA DURON SHP 10W30 (11 GAL)



### **DIAGNOSIS**

### Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

### Wear

Metal levels are typical for a new component breaking in.

#### Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components.


### **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

iAL)				Oct2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0103696		
Sample Date		Client Info		02 Oct 2023		
Machine Age	mls	Client Info		24193		
Dil Age	mls	Client Info		24193		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
-uel		WC Method	>2.0	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>100	38		
Chromium	ppm	ASTM D5185m	>20	1		
Nickel	ppm	ASTM D5185m	>4	<1		
Γitanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	<1		
Aluminum	ppm	ASTM D5185m	>20	24		
_ead	ppm	ASTM D5185m	>40	2		
Copper	ppm	ASTM D5185m	>330	18		
Γin	ppm	ASTM D5185m	>15	3		
/anadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	55		
Barium	ppm	ASTM D5185m	0	1		
Molybdenum	ppm	ASTM D5185m	50	63		
Manganese	ppm	ASTM D5185m	0	5		
Magnesium	ppm	ASTM D5185m	950	466		
Calcium	ppm	ASTM D5185m	1050	1707		
Phosphorus	ppm	ASTM D5185m	995	926		
Zinc	ppm	ASTM D5185m	1180	1258		
Sulfur	ppm	ASTM D5185m	2600	3071		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<u>41</u>		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	68		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.3		
Nitration	Abs/cm	*ASTM D7624	>20	8.1		
O 16 11		*ASTM D7415	>30	20.9		
Sulfation	Abs/.1mm	AOTIVI D7+13				
FLUID DEGRAD			limit/base	current	history1	history2
FLUID DEGRA					history1	history2
Sulfation  FLUID DEGRAE  Oxidation  Base Number (BN)	DATION	method	limit/base	current	ĺ	,



## **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: PCA0103696 : 05980314 : 10697609

: 16 Oct 2023 Received Diagnosed : 18 Oct 2023 Diagnostician : Don Baldridge Test Package : FLEET

6813 Chrisphalt Drive

Bath Borough, PA US 18014

Contact: Stephen Mackes smackes@transervice.com T: (610)837-8103

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: TSV1365 [WUSCAR] 05980314 (Generated: 10/19/2023 16:48:06) Rev: 1

Contact/Location: Stephen Mackes - TSV1365

F: (610)837-8105