

# **PROBLEM SUMMARY**

Sample Rating Trend



L-9 62 DISTRIBUTION

Component **Gearbox** 

PETRO CANADA ENDURATEX EP 460 (20 GAL)

**COMPONENT CONDITION SUMMARY** 

No relevant graphs to display

## RECOMMENDATION

We suspect abnormal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATION	C TEST	RESULT	S			
Sample Status				ABNORMAL	NORMAL	NORMAL
Dehris	scalar	*Vigual	NONE	▲ MODER	NONE	NONE

Customer Id: CERCLA Sample No.: PCA0091819 Lab Number: 05996833 Test Package: PLANT

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

28 Apr 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 24 Oct 2022 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 03 Aug 2022 Diag: Aaron Black

DEGRADATION



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend



L-9 62 DISTRIBUTION

Component

Gearbox

PETRO CANADA ENDURATEX EP 460 (20 GAL)

### DIAGNOSIS

### Recommendation

We suspect abnormal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

Moderate concentration of visible dirt/debris present in the oil.

## **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

GAL)		lec2017 Dec20	18 Aug2019 May2020 Au	g2020 May2021 Feb2022 Aug2022	Apr2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0091819	PCA0091868	PCA0080525
Sample Date		Client Info		27 Oct 2023	28 Apr 2023	24 Oct 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METAL	.S	method	limit/base	current	history1	history2
PQ		ASTM D8184		22	19	
Iron	ppm	ASTM D5185m	>200	32	38	59
Chromium	ppm	ASTM D5185m	>15	0	<1	1
Nickel	ppm	ASTM D5185m	>15	0	0	<1
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	0	0	<1
Copper	ppm	ASTM D5185m	>200	0	<1	<1
Tin	ppm	ASTM D5185m	>25	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	55	33	32	27
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0	0	<1	<1
Magnesium	ppm	ASTM D5185m	2	0	0	<1
Calcium	ppm	ASTM D5185m	6	0	0	0
Phosphorus	ppm	ASTM D5185m	240	406	481	473
Zinc	ppm	ASTM D5185m	3	4	1	<1
Sulfur	ppm	ASTM D5185m	10310	5335	6759	7066
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m		1	2	2
Sodium	ppm	ASTM D5185m		0	0	<1
Potassium	ppm	ASTM D5185m	>20	1	1	<1
FLUID DEGRAI	OITAC	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.5	1.51	1.48	1.04
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	▲ MODER	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Constitution of NATA		*\ /! I	0.0	NEO	NIEO	NEO

**Emulsified Water** 

\*Visual

>0.2

scalar

scalar \*Visual

NEG

**NEG** 

NEG

NEG

ion: BEGICE JAMES VEGERCLA



## **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

Test Package : PLANT

: PCA0091819 : 05996833 : 10725193

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 02 Nov 2023 Received Diagnosed : 07 Nov 2023 : Jonathan Hester Diagnostician

CERTAINTEED VINYL PLANT

2651 PENNY RD CLAREMONT, NC US 28613

F: (828)459-3329

Contact: BRUCE JAMES

bruce.a.james@saint-gobain.com T: (828)459-3320

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)