


OIL ANALYSIS REPORT

Sample Rating Trend







Machine Id 427176 Component

Transmission (Auto)

DEXRON III (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.

				Nov2023		
SAMPLE INFORM	AOITAN	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0094106		
Sample Date		Client Info		01 Nov 2023		
Machine Age	mls	Client Info		365932		
Dil Age	mls	Client Info		365932		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
WEAR METALS	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>160	28		
Chromium	ppm	ASTM D5185m	>5	<1		
Nickel	ppm	ASTM D5185m	>5	0		
Γitanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>50	6		
_ead	ppm	ASTM D5185m	>50	6		
Copper	ppm	ASTM D5185m	>225	56		
Γin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		84		
Barium	ppm	ASTM D5185m		5		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		439		
Phosphorus	ppm	ASTM D5185m		433		
Zinc	ppm	ASTM D5185m		33		
Sulfur	ppm	ASTM D5185m		1556		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	4		
Sodium	ppm	ASTM D5185m		6		
Potassium	ppm	ASTM D5185m	>20	1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPE	RTIES	method	limit/base	current	history1	history2




OIL ANALYSIS REPORT





SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image

GRAPHS



Non-ferrous Metals









Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10729203 Test Package : FLEET

: 06000843

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: GFL0094106

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Nov 2023 Diagnosed : 09 Nov 2023 Diagnostician : Sean Felton

GFL Environmental - 983 - Sugar Land Hauling 16011 West Belfort Street

Sugar Land, TX US 77498

Contact: TECHNICIAN ACCOUNT

wcgfldemo@gmail.com T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: