


OIL ANALYSIS REPORT

Inactive Off Road **E00**

Component

Left Final Drive

PETRO CANADA PRODURO TO-4 SAE 50 (--- GAL)



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Gear wear is indicated. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

GAL)				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0109782		
Sample Date		Client Info		07 Nov 2023		
Machine Age	hrs	Client Info		32373		
Oil Age	hrs	Client Info		32373		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>500	△ 623		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m	>10	<1		
Fitanium	ppm	ASTM D5185m		1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	22		
ead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	<1		
Γin	ppm	ASTM D5185m	>10	0		
/anadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	0		
Barium	ppm	ASTM D5185m	0	2		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m	0	5		
Magnesium	ppm	ASTM D5185m	9	19		
Calcium	ppm	ASTM D5185m	3114	2826		
Phosphorus	ppm	ASTM D5185m	1099	1328		
Zinc	ppm	ASTM D5185m	1245	1434		
Sulfur	ppm	ASTM D5185m	7086	9108		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	60		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	5		
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	3.27	1.57		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	MODER		
ellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
ree Water	scalar	*Visual		NEG		
19:19) Rev: 1					Submitted By:	MATT MANOL



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

: 10736808 Unique Number Test Package : MOB 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0109782 Received : 09 Nov 2023 : 06003046 Diagnosed : 13 Nov 2023 Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

G LOPES CONSTRUCTION

565 WINTHROP ST TAUNTON, MA US 02780

Contact: BUTCH MCGRATH

bmcgrath@glopes.com

T: F:

Submitted By: MATT MANOLI