

FUEL REPORT

Manistee bottom of fuel cell

Component

Diesel Fuel

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.

Corrosion


All metal levels are normal indicating no corrosion in the system.

Contaminants

The water content is negligible. There is no indication of any contamination in the fuel.

Fuel Condition


The condition of the fuel is acceptable for the time in service.




| SAMPLE INFORM | MATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|----------|----------|
| Sample Number | | Client Info | | GFL0096118 | | |
| Sample Date | | Client Info | | 10 Nov 2023 | | |
| Machine Age | hrs | Client Info | | 0 | | |
| Sample Status | | | | NORMAL | | |
| PHYSICAL PROP | ERTIES | method | limit/base | current | history1 | history2 |
| Visc @ 40°C | cSt | ASTM D445 | | 2.79 | | |
| SULFUR CONT | ΓENT | method | limit/base | current | history1 | history2 |
| Sulfur | ppm | ASTM D5185m | | 8 | | |
| CONTAMINAN | TS | method | limit/base | current | history1 | history2 |
| Silicon | ppm | ASTM D5185m | <1.0 | <1 | | |
| Sodium | ppm | ASTM D5185m | <0.1 | 1 | | |
| Potassium | ppm | ASTM D5185m | <0.1 | 10 | | |
| Water | % | ASTM D6304 | < 0.05 | 0.004 | | |
| ppm Water | ppm | ASTM D6304 | < 500 | 48.3 | | |
| HEAVY METAL | .S | method | limit/base | current | history1 | history2 |
| Aluminum | ppm | ASTM D5185m | < 0.1 | 2 | | |
| Nickel | ppm | ASTM D5185m | <0.1 | 0 | | |
| Lead | ppm | ASTM D5185m | <0.1 | 0 | | |
| Vanadium | ppm | ASTM D5185m | <0.1 | <1 | | |
| Iron | ppm | ASTM D5185m | <0.1 | 0 | | |
| Calcium | ppm | ASTM D5185m | <0.1 | <1 | | |
| Magnesium | ppm | ASTM D5185m | <0.1 | 3 | | |
| Phosphorus | ppm | ASTM D5185m | < 0.1 | 0 | | |
| Zinc | ppm | ASTM D5185m | <0.1 | 0 | | |
| SAMPLE IMAG | ES | method | limit/base | current | history1 | history2 |
| Color | | | | | no image | no image |
| Bottom | | | | | no image | no image |



FUEL REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10742531

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0096118 : 06008769

Received Diagnosed Diagnostician : Jonathan Hester

: 15 Nov 2023 : 30 Nov 2023 GFL Environmental - 631 - Manistee 407 Renaissance Dr

Manistee, MI US 49660

Contact: MITCH HERSHBERGER

Test Package : FLEET (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T: (231)624-0848

F: