


PROBLEM SUMMARY


Walgreens - Tractor [Walgreens - Tractor] 136A63370


Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 GAL)



COMPONENT CONDITION SUMMARY





RECOMMENDATION

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	
Nickel	ppm	ASTM D5185m	>4	<u>^</u> 7	

Customer Id: TSV1366 Sample No.: PCA0105436 Lab Number: 06011856 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Walgreens - Tractor [Walgreens - Tractor] 136A63370

Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 G



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

Exhaust valve wear is indicated.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

						\
GAL)				Oct2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0105436		
Sample Date		Client Info		30 Oct 2023		
Machine Age	mls	Client Info		102889		
Oil Age	mls	Client Info		25000		
Oil Changed	11110	Client Info		Changed		
Sample Status		Oliciti iilio		ABNORMAL		
CONTAMINAT	TION!	method	limit/base	current	history1	history2
	ION					
Fuel		WC Method	>2.0	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	51		
Chromium	ppm	ASTM D5185m	>20	3		
Nickel	ppm	ASTM D5185m	>4	<u>^</u> 7		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	<1		
Aluminum	ppm	ASTM D5185m	>20	23		
Lead	ppm	ASTM D5185m	>40	4		
Copper	ppm	ASTM D5185m	>330	17		
Tin	ppm	ASTM D5185m	>15	2		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	10		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	50	79		
Manganese	ppm	ASTM D5185m	0	2		
Magnesium	ppm	ASTM D5185m	950	1100		
Calcium	ppm	ASTM D5185m	1050	1420		
Phosphorus	ppm	ASTM D5185m	995	1186		
Zinc	ppm	ASTM D5185m	1180	1559		
Sulfur	ppm	ASTM D5185m	2600	3422		
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	18		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	60		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.5		
Nitration	Abs/cm	*ASTM D7624	>20	9.4		
Sulfation	Abs/.1mm	*ASTM D7415		22.0		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414		18.9		
Base Number (BN)	mg KOH/g		720	6.5		
Dase Mulliber (BIN)	ilig KUH/g	A3 1 W D2030		0.5		



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: PCA0105436 : 06011856 : 10751000 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 20 Nov 2023 : 21 Nov 2023 : Sean Felton

Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Transervice - Shop 1366 - Berkeley-Woodland

2370 East Main Street Woodland, CA US 95776 Contact: Gary Mann

gmann@transervice.com T: (530)666-7771 F: (530)406-7971

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)