


PROBLEM SUMMARY






Machine Id
7808M
Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS						
Sample Status				ABNORMAL	NORMAL	NORMAL
Silicon	ppm	ASTM D5185m	>25	^ 27	5	6

Customer Id: GFL410 Sample No.: GFL0104383 Lab Number: 06027366 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

15 Nov 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



28 Sep 2022 Diag: Don Baldridge

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT





7808M Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

N SHP 15W40 (-	GAL)	Sej	2022	Nov2023 Dec20	23	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0104383	GFL0059231	GFL0059200
Sample Date		Client Info		01 Dec 2023	15 Nov 2023	28 Sep 2022
Machine Age	mls	Client Info		126551	125554	106976
Oil Age	mls	Client Info		125554	18578	106976
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
uel		WC Method	>3.0	<1.0	<1.0	<1.0
Vater		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>90	27	7	27
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>2	1	0	0
Titanium	ppm	ASTM D5185m	>2	<1	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	2	4	2
_ead	ppm	ASTM D5185m	>40	<1	0	2
Copper	ppm	ASTM D5185m	>330	108	11	1
Γin	ppm	ASTM D5185m	>15	3	<1	0
/anadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	108	2	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	65	56	52
Manganese	ppm	ASTM D5185m	0	4	<1	<1
Magnesium	ppm	ASTM D5185m	1010	359	883	833
Calcium	ppm	ASTM D5185m	1070	1823	1004	825
Phosphorus	ppm	ASTM D5185m	1150	1147	981	929
Zinc	ppm	ASTM D5185m	1270	1316	1182	1041
Sulfur	ppm	ASTM D5185m	2060	4368	3016	2508
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<u> </u>	5	6
Sodium	ppm	ASTM D5185m		0	3	6
Potassium	ppm	ASTM D5185m	>20	4	6	0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>6	0.1	0.2	0.6
	Abs/cm	*ASTM D7624	>20	5.8	5.3	13.0
Nitration	ADS/CITI					
Nitration Sulfation	Abs/.1mm	*ASTM D7415	>30	17.9	18.7	26.5
	Abs/.1mm		>30 limit/base		18.7 history1	26.5 history2
Sulfation	Abs/.1mm			17.9		



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


Base Number	
8.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
4.0	
2.0	
0.0	23
Sep28/72	Nov15/23


Nov15/23


Viscosity @ 100°C




GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number

Unique Number Test Package : FLEET

: GFL0104383 : 06027366 : 10777157

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Dec 2023 Diagnosed : 11 Dec 2023

Diagnostician : Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 410 - Michigan West

39000 Van Born Rd Wayne, MI US 48184

history2

Contact: Belal Dgheish bdgheish@gflenv.com T: (734)714-2340

Submitted By: Belal Dgheish