

OIL ANALYSIS REPORT



KEMP QUARRIES / KEMP STONE - FAIRLAND [66087] **WL071**

Component **Rear Right Final Drive**

PETRO CANADA PRODURO TO-4 SAE 50 (--- GAL)





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We recommend an early resample to monitor this condition. (Customer Sample Comment: PM-3 sampled fluid)

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORI	NOITAN	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0086234	PCA0086329	PCA0086055
Sample Date		Client Info		06 Dec 2023	20 Jun 2023	06 Apr 2023
Machine Age	hrs	Client Info		32462	32119	31788
Oil Age	hrs	Client Info		32462	32119	31788
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	61	57	25
Chromium	ppm	ASTM D5185m	>10	0	0	<1
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m	>15	0	<1	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	1	<1	1
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>75	14	12	5
Tin	ppm	ASTM D5185m	>8	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES	1-1-	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	4	0	0
Barium	ppm	ASTM D5185m	0	0	15	0
Molybdenum	ppm	ASTM D5185m	0	1	<1	<1
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	9	16	31	19
Calcium	ppm	ASTM D5185m	3114	3083	3047	3024
Phosphorus	ppm	ASTM D5185m	1099	939	1081	1015
Zinc	ppm	ASTM D5185m	1245	1192	1377	1267
Sulfur	ppm	ASTM D5185m	7086	4983	6107	5973
CONTAMINAN		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	21	15	9
Sodium	ppm	ASTM D5185m		0	<1	<1
Potassium	ppm	ASTM D5185m	>20	2	0	0
Water	%	ASTM D6304		<u> </u>		
ppm Water	ppm	ASTM D6304	>2000	7940		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	MODER	MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	0.2%	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: PCA0086234 : 06034198 : 10789427

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 18 Dec 2023 Diagnostician : Sean Felton

: 13 Dec 2023

Test Package : MOB 1 (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Kemp Quarries - Kemp Stone - Fairland

18350 S 590 Rd Fairland, OK US 74343

Contact:

fairland@kempstone.com T:

F: