


OIL ANALYSIS REPORT

OAKDALE JOHN DEERE 1DW644LZHLL707702

Component

Rear Differential

JOHN DEERE HY-GARD HYD/TRANS (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

iAL)				Dec2023		
SAMPLE INFOR	RMATION	Method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0107187		
Sample Date		Client Info		06 Dec 2023		
Machine Age	hrs	Client Info		8872		
Oil Age	hrs	Client Info		2		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINA	TION	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG		
WEAR METAI	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	53		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>25	59		
Copper	ppm	ASTM D5185m	>100	21		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	6	14		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	0	1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	145	106		
Calcium	ppm	ASTM D5185m	3570	3106		
Phosphorus	ppm	ASTM D5185m	1290	979		
Zinc	ppm	ASTM D5185m	1640	1100		
Sulfur	ppm	ASTM D5185m		3999		
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	25		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	0		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Free Water	scalar	*Visual		NEG		
	Julia					



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

Test Package : MOB 1

: PCA0107187 : 06038850 : 10794079

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 18 Dec 2023 : 20 Dec 2023 Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **CENTRAL VALLEY AG**

5707 LANGWORTH OAKDALE, CA US 95361

Contact: LAB TECH m-labtech@outlook.com

> T: F: