

# **OIL ANALYSIS REPORT**

Area FLEET

Volvo. 2227073 (S/N N631485. 2227073)

**Transmission** 

{not provided} (--- GAL)

# Sample Rating Trend



# DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

All component wear rates are normal.

## Contamination

There is no indication of any contamination in the


## **Fluid Condition**


The condition of the fluid is acceptable for the time in service.

				Jan2024		
OAMBLE INCODE	MATION				12.4	111
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0116222		
Sample Date		Client Info		08 Jan 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	49		
Chromium	ppm	ASTM D5185m	>10	1		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>50	<1		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>200	34		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		33		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		785		
Phosphorus	ppm	ASTM D5185m		668		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		4382		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	49		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
<b>Emulsified Water</b>	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		





# **OIL ANALYSIS REPORT**





# **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10829888

: PCA0116222 : 06058506 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved Diagnosed

: 11 Jan 2024 : 12 Jan 2024

Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**PERDUE FARMS - DILLON** 

2047 HWY 9 WEST DILLON, SC US 29536

Contact: KEVIN HOOKS kevin.hooks@perdue.com

Submitted By: KEVIN HOOKS

T: (843)841-8069 F: (843)841-8070

Report Id: PERDILSC [WUSCAR] 06058506 (Generated: 01/15/2024 15:31:56) Rev: 1

Page 2 of 2