


PROBLEM SUMMARY




Machine Id **413059**

Component

Transmission (Auto)

{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where dirt can enter the system. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. (Customer Sample Comment: Transmission)

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE	NORMAL	ABNORMAL			
Silicon	ppm	ASTM D5185m	>20	6 7	20	<u>^</u> 24			

Customer Id: GFL983 Sample No.: GFL0105544 Lab Number: 06060517 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS Action Status Date Done By Description Resample -- -- ? We recommend an early resample to monitor this condition. Information Required -- -- ? Please specify the brand, type, and viscosity of the oil on your next sample. Check Dirt Access -- ? We advise that you check all areas where dirt can enter the system.

HISTORICAL DIAGNOSIS

02 Aug 2023 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



13 Jul 2023 Diag: Don Baldridge

DIKT




Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Elemental level of silicon (Si) above normal. The condition of the fluid is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample





Machine Id **413059**

Component

Transmission (Auto)

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. (Customer Sample Comment: Transmission)

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

				Aug 2023 Jan 20	24	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0105544	GFL0085498	GFL0085495
Sample Date		Client Info		08 Jan 2024	02 Aug 2023	13 Jul 2023
Machine Age	mls	Client Info		65172	45612	42909
Oil Age	mls	Client Info		65172	45612	42909
Oil Changed		Client Info		N/A	Changed	Changed
Sample Status				SEVERE	NORMAL	ABNORMAL
CONTAMINAT	ΓΙΟΝ	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	36	12	21
Chromium	ppm	ASTM D5185m	>5	0	<1	<1
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>5	0	0	0
Aluminum	ppm	ASTM D5185m	>50	9	7	18
Lead	ppm	ASTM D5185m	>50	<1	0	<1
Copper	ppm	ASTM D5185m	>225	9	5	4
Tin	ppm	ASTM D5185m	>10	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
	PPIII					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		12	59	348
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		2	<1	<1
Manganese	ppm	ASTM D5185m		1	<1	1
Magnesium	ppm	ASTM D5185m		6	9	0
Calcium	ppm	ASTM D5185m		2761	2483	51
Phosphorus	ppm	ASTM D5185m		975	956	1257
Zinc	ppm	ASTM D5185m		1091	974	0
Sulfur	ppm	ASTM D5185m		3380	3599	708
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	67	20	<u> </u>
Sodium	ppm	ASTM D5185m		2	<1	2
Potassium	ppm	ASTM D5185m	>20	0	0	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
.10.E4\ D 1				0	A D TEOLINIO	1441 40001141



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

Unique Number : 10831899 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0105544

: 06060517

Recieved : 12 Jan 2024 Diagnosed : 16 Jan 2024 Diagnostician : Don Baldridge GFL Environmental - 983 - Sugar Land Hauling 16011 West Belfort Street Sugar Land, TX

US 77498 Contact: Gino Griego ggriego@gflenv.com T: (720)999-0726

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)