PROBLEM SUMMARY

Sample Rating Trend


Component Diesel Engine Fluid DYNA-PLEX 21C 15W40 (--- GAL)

OIL

Machine Id NF324388

DIAGNOSTICS

COMPONENT CONDITION SUMMARY



🔺 Viscosity @ 100°C



RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE				
Fuel	%	ASTM D3524	>5	• 17.6				
Base Number (BN)	mg KOH/g	ASTM D2896		2 .4				
Visc @ 100°C	cSt	ASTM D445		9.8				

Customer Id: VALCHAMN Sample No.: PCA0069474 Lab Number: 06072584 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDE	ECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Fuel/injector System			?	We advise that you check the fuel injection system.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



Machine Id **NF324388**

Component Diesel Engine Fluid DYNA-PLEX 21C 15W40 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a high amount of fuel present in the oil.

Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The BN level is low. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0069474		
Sample Date		Client Info		01 Aug 2023		
Machine Age	mls	Client Info		15470		
Oil Age	mls	Client Info		5100		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	24		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>4	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>20	2		
Lead	ppm	ASTM D5185m	>40	4		
Copper	ppm	ASTM D5185m	>330	7		
Tin	ppm	ASTM D5185m	>15	2		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		6		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		47		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		749		
Calcium	ppm	ASTM D5185m		851		
Phosphorus	ppm	ASTM D5185m		780		
Zinc	ppm	ASTM D5185m		961		
Sulfur	ppm	ASTM D5185m		2397		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	9		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	4		
Fuel	%	ASTM D3524	>5	• 17.6		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.6		
Nitration	Abs/cm	*ASTM D7624	>20	12.4		
Sulfation	Abs/.1mm	*ASTM D7415	>30	34.1		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	46.9		
Base Number (BN)	mg KOH/g	ASTM D2896		2 .4		



ase 0.5

0.0

18 16

8 Aug1/23


Aug

Viscosity @ 100°C

OIL ANALYSIS REPORT

VISUAL





* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Certificate L2367

F:

T: (612)418-7048