


OIL ANALYSIS REPORT

Sample Rating Trend

VIS DEBRIS







443001

Component

Transmission (Auto)

PETRO CANADA DuraDrive HD Synthetic 668 (--- GAL)

DIAGNOSIS

Recommendation

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the fluid.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

nu Synthetic 666 (GAL)		Jan 2023	Jan 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0103273	GFL0070266	
Sample Date		Client Info		26 Jan 2024	30 Jan 2023	
Machine Age	hrs	Client Info		15627	14694	
Oil Age	hrs	Client Info		1200	2400	
Oil Changed		Client Info		Not Changd	Not Changd	
Sample Status				ABNORMAL	ABNORMAL	
CONTAMINATION	ON	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	
WEAR METALS	3	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>160	92	79	
Chromium	ppm	ASTM D5185m	>5	0	<1	
Nickel	ppm	ASTM D5185m	>5	0	0	
Γitanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m	>5	0	0	
Aluminum	ppm	ASTM D5185m	>50	31	22	
_ead	ppm	ASTM D5185m	>50	3	3	
Copper	ppm	ASTM D5185m	>225	10	8	
Γin	ppm	ASTM D5185m	>10	3	2	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		69	84	
Barium	ppm	ASTM D5185m		0	<1	
Molybdenum	ppm	ASTM D5185m		0	<1	
Manganese	ppm	ASTM D5185m		<1	<1	
Magnesium	ppm	ASTM D5185m		0	<1	
Calcium	ppm	ASTM D5185m		68	70	
Phosphorus	ppm	ASTM D5185m		219	216	
Zinc	ppm	ASTM D5185m		7	11	
Sulfur	ppm	ASTM D5185m		1075	1147	
CONTAMINANT	ΓS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	6	
Sodium	ppm	ASTM D5185m		7	4	
Potassium	ppm	ASTM D5185m	>20	2	2	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	▲ MODER	▲ MODER	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	





OIL ANALYSIS REPORT




FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	34	36.9	37.0	
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

GRAPHS









Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10857311 Test Package : FLEET

: GFL0103273 : 06075220

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 30 Jan 2024 Diagnosed

: 01 Feb 2024 Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 836 - Kansas City Hauling

7801 East Truman Road Kansas City, MO US 64126

Contact: Robert Hart rhart@gflenv.com T: (580)461-1509