




(69J4UN) 929096-205270

Component **Hydraulic System**

PETRO CANADA HYDREX MV 46 (--- GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample. Moderate concentration of visible dirt/debris present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in

0.11.151.5.11.150.5	=					
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0108103		
Sample Date		Client Info		02 Feb 2024		
Machine Age	hrs	Client Info		4310		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	38		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m	>4	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>5	<1		
Lead	ppm	ASTM D5185m	>4	0		
Copper	ppm	ASTM D5185m	>15	0		
Tin	ppm	ASTM D5185m	>4	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	0	3		
Manganese	ppm	ASTM D5185m	1	<1		
Magnesium	ppm	ASTM D5185m	0	40		
Calcium	ppm	ASTM D5185m	50	153		
Phosphorus	ppm	ASTM D5185m	330	383		
Zinc	ppm	ASTM D5185m	430	516		
Sulfur	ppm	ASTM D5185m	760	1049		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	3		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	2		
FLUID DEGRAI	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.70	0.52		




OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	▲ MODER		
Debris	scalar	*Visual	NONE	MODER		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	A CTM D 44E	45.4	47.8		
V130 @ 40 0	COL	ASTM D445	45.4	47.8		
SAMPLE IMAG		method	limit/base	current	history1	history2
SAMPLE IMAG					history1	history2
SAMPLE IMAG					no image	no image
SAMPLE IMAG Color Bottom					no image	no image













Laboratory Sample No. Lab Number : 06088110 Unique Number : 10875555

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0108103

Received **Tested** Diagnosed

: 13 Feb 2024 : 15 Feb 2024

: 15 Feb 2024 - Don Baldridge

GFL Environmental - 823 - Central Missouri Hauling 24461 Oak Grove Lane Sedalia, MO

US 65301 Contact: Terry Randolph trandolph@gflenv.com

T: (660)631-2116

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Test Package: FLEET (Additional Tests: PrtCount)

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)