

OIL ANALYSIS REPORT

Sample Rating Trend






KEMP QUARRIES / MUSKOGEE SAND [68593] WL109 Component

Front Left Final Drive

PETRO CANADA PRODURO TO-4 SAE 50 (--- GAL)



DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. (Customer Sample Comment: PM-2 sampled fluid)

Wear

All component wear rates are normal.

Contamination


There is no indication of any contamination in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.



OIL ANALYSIS REPORT





Certificate L2367