


# **OIL ANALYSIS REPORT**

#### Sample Rating Trend







# JOHN DEERE 243

Component

Hydraulic System

Hydraulic System

JOHN DEERE HY-GARD HYD/TRANS (--- GAL)

### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the fluid.


#### **Fluid Condition**


The condition of the fluid is acceptable for the time in service.

iAL)			Sep2023	Feb2024		
SAMPLE INFOF	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0107161	PCA0105094	
Sample Date		Client Info		08 Feb 2024	27 Sep 2023	
Machine Age	hrs	Client Info		2779	2454	
Oil Age	hrs	Client Info		359	2454	
Oil Changed		Client Info		N/A	Not Changd	
Sample Status				NORMAL	NORMAL	
CONTAMINAT	ΓΙΟΝ	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	5	0	
Chromium	ppm	ASTM D5185m	>10	0	1	
Nickel	ppm	ASTM D5185m	>10	0	<1	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>10	1	0	
Lead	ppm	ASTM D5185m	>10	0	<1	
Copper	ppm	ASTM D5185m	>75	4	<1	
Tin	ppm	ASTM D5185m	>10	0	0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	6	21	0	
Barium	ppm	ASTM D5185m	0	0	0	
Molybdenum	ppm	ASTM D5185m	0	<1	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m	145	7	3	
Calcium	ppm	ASTM D5185m	3570	795	106	
Phosphorus	ppm	ASTM D5185m	1290	817	640	
Zinc	ppm	ASTM D5185m	1640	985	857	
Sulfur	ppm	ASTM D5185m		2283	1647	
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	4	1	
Sodium	ppm	ASTM D5185m		0	0	
Potassium	ppm	ASTM D5185m	>20	4	4	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	
<b>Emulsified Water</b>	scalar	*Visual	>0.1	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	



## **OIL ANALYSIS REPORT**









Laboratory Sample No.

Lab Number : 06098047 Unique Number: 10896277 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0107161 Received : 22 Feb 2024 : 23 Feb 2024 **Tested** 

Diagnosed

: 25 Feb 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**CENTRAL VALLEY AG** 

5707 LANGWORTH OAKDALE, CA US 95361

Contact: S MCHENRY smchenry@cv-ag.com T: (209)630-8094