

OIL ANALYSIS REPORT

Sample Rating Trend





KEMP QUARRIES / PRYOR STONE [64441] WL103 Component

Rear Right Final Drive

PETRO CANADA PRODURO TO-4 SAE 50 (--- GAL)

Sample Number

Sample Date

Machine Age

Oil Changed

Sample Status

Oil Age

Water

Iron

Nickel

Silver

Lead

Tin

Copper


Vanadium

Cadmium

Titanium

Aluminum

Chromium



ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	<1	0	0
Barium	ppm	ASTM D5185m	0	0	8	0
Molybdenum	ppm	ASTM D5185m	0	1	2	<1
Manganese	ppm	ASTM D5185m	0	0	<1	<1
Magnesium	ppm	ASTM D5185m	9	15	17	11
Calcium	ppm	ASTM D5185m	3114	3123	3234	2275
Phosphorus	ppm	ASTM D5185m	1099	889	907	819
Zinc	ppm	ASTM D5185m	1245	1056	1055	939
Sulfur	ppm	ASTM D5185m	7086	6836	9256	4767

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	13	15	4
Sodium	ppm	ASTM D5185m		0	0	1
Potassium	ppm	ASTM D5185m	>20	1	1	0

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. (Customer Sample Comment: Pm4 performed. All oil samples taken. Engine oil, transmission oil, and all filters changed.)

Wear

All component wear rates are normal.

Contamination


There is no indication of any contamination in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.



OIL ANALYSIS REPORT





Report Id: KEMPRY [WUSCAR] 06121832 (Generated: 03/21/2024 12:12:40) Rev: 1

Certificate L2367