


OIL ANALYSIS REPORT

Nickelson

Sany SY365 SY036MCB00618 Nickelson

Hydraulic System

CITGO AW HYDRAULIC ISO 46 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


Fluid Condition


The condition of the fluid is acceptable for the time in service.

					.,	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0115502	LW0008311	LW0008242
Sample Date		Client Info		04 Apr 2024	28 Feb 2024	19 Dec 2023
Machine Age	hrs	Client Info		2845	2576	2158
Oil Age	hrs	Client Info		2845	2576	2158
Oil Changed	0	Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	5	3	9
Chromium	ppm	ASTM D5185m	>10	1	<1	<1
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		1	<1	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>10	2	<1	2
Lead	ppm	ASTM D5185m	>10	<1	3	0
Copper	ppm	ASTM D5185m		3	2	5
Tin	ppm	ASTM D5185m	>10	1	0	0
Vanadium	ppm	ASTM D5185m	>10	<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
	рріп	AOTIVI DOTOSIII				
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		63	59	3
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		4	3	4
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		48	47	14
Calcium	ppm	ASTM D5185m		1892	1841	316
Phosphorus	ppm	ASTM D5185m		856	788	464
Zinc	ppm	ASTM D5185m		1047	909	608
Sulfur	ppm	ASTM D5185m		2703	2222	1325
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	5	1
Sodium	ppm	ASTM D5185m		0	1	0
Potassium	ppm	ASTM D5185m	>20	2	0	<1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG



OIL ANALYSIS REPORT









Certificate 12367

Sample No. Lab Number : 06143467

: PCA0115502

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Unique Number : 10968275 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 09 Apr 2024

Tested : 10 Apr 2024 Diagnosed

: 12 Apr 2024 - Jonathan Hester

US 60411-7728 Contact: Mike Korbelik mike@chicagomachineryinc.com T: (708)758-2060

CHICAGO MACHINERY INC

3142 EAST LINCOLN

LYNWOOD, IL

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)