


# **OIL ANALYSIS REPORT**

## Sample Rating Trend









# KEMP QUARRIES / HULBERT WL067

Component
Front Right Final Drive
Fluid

MOBIL MOBILTRANS HD 50 (--- GAL)

## DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

There is no indication of any contamination in the oil.

### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

ID OO ( GAL)						
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0085907	PCA0086821	PCA0048637
Sample Date		Client Info		05 Apr 2024	28 Jul 2023	24 Sep 2021
Machine Age	hrs	Client Info		32148	32149	29147
Oil Age	hrs	Client Info		28617	0	0
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	361	246	58
Chromium	ppm	ASTM D5185m	>10	1	<1	<1
Nickel	ppm	ASTM D5185m	>5	<1	0	<1
Titanium	ppm	ASTM D5185m	>15	<1	0	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	5	2	1
Lead	ppm	ASTM D5185m	>10	<1	<1	0
Copper	ppm	ASTM D5185m	>75	4	2	3
Tin	ppm	ASTM D5185m	>8	<1	<1	0
Antimony	ppm	ASTM D5185m	>50			3
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		1	2	9
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		3	2	5
Manganese	ppm	ASTM D5185m		3	2	<1
Magnesium	ppm	ASTM D5185m		38	34	27
Calcium	ppm	ASTM D5185m		3129	2834	2899
Phosphorus	ppm	ASTM D5185m		1034	985	958
Zinc	ppm	ASTM D5185m		1297	1220	1109
Sulfur	ppm	ASTM D5185m		6153	5622	4279
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	27	22	14
Sodium	ppm	ASTM D5185m		2	<1	<1
Potassium	ppm	ASTM D5185m	>20	2	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	analar	*\/;	NODM	NODMI	NODM	NODM

**NORML** 

NEG

**NEG** 

NORML

NEG

NEG

NORML

>0.2

scalar \*Visual

scalar \*Visual

\*Visual

scalar

Odor


**Emulsified Water** 

NORML


NEG



## **OIL ANALYSIS REPORT**









툂 100

50

Copper (ppm)







Certificate 12367

Sample No.

Lab Number : 06149724

Test Package : MOB 1

: PCA0085907 Unique Number : 10979802

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 15 Apr 2024 **Tested** : 16 Apr 2024 Diagnosed

: 16 Apr 2024 - Wes Davis

Kemp Quarries - Kemp Stone - Hulbert 17801 Hwy 80

Hulbert, OK US 74441

Contact: hulbert@kempstone.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: KEMHUL [WUSCAR] 06149724 (Generated: 04/16/2024 15:50:26) Rev: 1

Submitted By:

T:

F: