


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

MG / south feed conv Gearbox

MOBIL MOBIL MOBILGEAR XMP 220 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. Resample at the next service interval to monitor.

Gear wear is indicated.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.


Fluid Condition

The condition of the oil is acceptable for the time in service.

AL)		Apr202	1 Jan 2022	Mar2022 Ag	or2024	
SAMPLE INFO	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0082739	PCA0069299	PCA0058470
Sample Date		Client Info		03 Apr 2024	28 Mar 2022	18 Jan 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	Not Changd	N/A
Sample Status				ABNORMAL	NORMAL	ATTENTION
CONTAMINA	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	176	9	173
Chromium	ppm	ASTM D5185m	>10	<1	0	<1
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	<1
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	<u> </u>	2	3
Lead	ppm	ASTM D5185m	>50	<1	0	<1
Copper	ppm	ASTM D5185m	>200	5	5	2
Tin	ppm	ASTM D5185m	>10	<1	0	0
Antimony	ppm	ASTM D5185m	>5			0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	66	62	24
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m	0	<1	0	0
Manganese	ppm	ASTM D5185m		2	0	2
Magnesium	ppm	ASTM D5185m		4	0	1
Calcium	ppm	ASTM D5185m	0	8	2	5
Phosphorus	ppm	ASTM D5185m	485	261	292	327
Zinc	ppm	ASTM D5185m	0	5	0	0
Sulfur	ppm	ASTM D5185m		15394	7813	14870
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	▲ 63	18	22
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	4	0	<1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water			- 0.=			y: senjezimm



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No. Lab Number : 06155332 Unique Number : 10990755

Test Package : FLEET

: PCA0082739

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 19 Apr 2024 **Tested**

: 24 Apr 2024 Diagnosed : 24 Apr 2024 - Sean Felton

AVR - APPLE VALLEY READY MIX 14698 GALAXY AVE APPLE VALLEY, MN

US 55124 Contact: COLE DAMBROTEN

coledambroten@avrconcrete.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: