


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id BV / north bottem belt Gearbox

MOBIL MOBIL GEAR XMP 220 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.

AL)		Apr2021	Feb2022	Feb 2022 Mar 2022	Mar2024	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0082718	PCA0069562	PCA0058452
Sample Date		Client Info		28 Mar 2024	28 Mar 2022	14 Feb 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	Not Changd	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	_S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>200	19	7	43
Chromium	ppm	ASTM D5185m	>10	<1	0	0
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	2	2	<1
.ead	ppm	ASTM D5185m	>50	<1	0	0
Copper	ppm	ASTM D5185m	>200	<1	0	0
īn	ppm	ASTM D5185m	>10	<1	0	<1
/anadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	69	52	12
Barium	ppm	ASTM D5185m		0	0	0
Nolybdenum	ppm	ASTM D5185m	0	<1	0	0
Manganese	ppm	ASTM D5185m		<1	0	<1
/lagnesium	ppm	ASTM D5185m		2	0	0
Calcium	ppm	ASTM D5185m	0	2	<1	13
Phosphorus	ppm	ASTM D5185m	485	388	294	321
Zinc	ppm	ASTM D5185m	0	3	0	8
Sulfur	ppm	ASTM D5185m		9955	7788	10247
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	43	21	36
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	2	0	0
VISUAL		method	limit/base	current	history1	history2
Vhite Metal	scalar	*Visual	NONE	NONE	NONE	NONE
'ellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
mulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
ree Water	scalar	*Visual		NEG	NEG	NEG





OIL ANALYSIS REPORT






GRAPHS











Certificate 12367

Laboratory Sample No.

: PCA0082718 Lab Number : 06155343 Unique Number : 10990766 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

Received : 19 Apr 2024 **Tested** Diagnosed

: 22 Apr 2024 : 22 Apr 2024 - Wes Davis

14698 GALAXY AVE APPLE VALLEY, MN US 55124

Contact: COLE DAMBROTEN coledambroten@avrconcrete.com

AVR - APPLE VALLEY READY MIX

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: