


# **OIL ANALYSIS REPORT**



**NORMAL** 



Machine Id BV / south bottom belt Gearbox

MOBIL MOBIL MOBILGEAR XMP 220 (--- GAL)

# DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the

## **Fluid Condition**

The condition of the oil is acceptable for the time in service.

A=/						
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0082720	PCA0058451	PCA0043170
Sample Date		Client Info		28 Mar 2024	14 Feb 2022	12 Apr 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	N/A	Changed
Sample Status				NORMAL	ABNORMAL	ABNORMAL
CONTAMINA	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAI	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	11	63	47
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>10	<1	0	<1
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>25	2	3	2
Lead	ppm	ASTM D5185m	>50	<1	0	<1
Copper	ppm	ASTM D5185m	>200	<1	0	<1
Tin	ppm	ASTM D5185m	>10	<1	<1	0
Antimony	ppm	ASTM D5185m	>5			0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	45	17	12
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m	0	<1	<1	0
Manganese	ppm	ASTM D5185m		<1	2	1
Magnesium	ppm	ASTM D5185m		1	4	2
Calcium	ppm	ASTM D5185m	0	<1	33	7
Phosphorus	ppm	ASTM D5185m	485	270	315	289
Zinc	ppm	ASTM D5185m	0	0	34	16
Sulfur	ppm	ASTM D5185m		7153	14470	12489
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	30	<b>▲</b> 87	<b>△</b> 70
Sodium	ppm	ASTM D5185m		0	1	1
Potassium	ppm	ASTM D5185m	>20	2	0	13
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	VLITE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	analau	*\/:	NODMI	NODMI	NODM	NODM

NORML

>0.2

scalar \*Visual

scalar \*Visual

scalar

\*Visual

**NORML** 

NEG

**NEG** 

Odor

**Emulsified Water** 

NORML


NEG


Submitted By: senjeczimmer

NORML





# **OIL ANALYSIS REPORT**






## **GRAPHS**











Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Lab Number : 06155344 Unique Number : 10990767

: PCA0082720 Test Package : FLEET

Received Tested Diagnosed

: 19 Apr 2024 : 24 Apr 2024

: 24 Apr 2024 - Jonathan Hester

**AVR - APPLE VALLEY READY MIX** 14698 GALAXY AVE APPLE VALLEY, MN US 55124

Contact: COLE DAMBROTEN coledambroten@avrconcrete.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: