

# **OIL ANALYSIS REPORT**

Cozzi MH1

# **COZZI SENNEBOGAN 825 (S/N 825.0.2570)**

**Front Axle** 

CITGO PREMIUM GEAR 80W90 (--- GAL)

# Sample Rating Trend



# DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

## Contamination

There is no indication of any contamination in the


# **Fluid Condition**


The condition of the oil is acceptable for the time in service.


		Nov2021 Jur	n2022 Sep2022 Nov2022	Feb2023 Apr2023 Aug2023 Nov20.	23 May2024	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0115572	LW0007634	LW0007302
Sample Date		Client Info		20 May 2024	03 Nov 2023	08 Aug 202
Machine Age	hrs	Client Info		12750	11548	10965
Oil Age	hrs	Client Info		12750	11548	10965
Oil Changed		Client Info		Not Changd	Not Changd	Not Change
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	19	5	4
Chromium	ppm	ASTM D5185m	>10	<1	0	0
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		<1	0	0
Aluminum	ppm	ASTM D5185m	>25	2	0	0
Lead	ppm	ASTM D5185m	>25	<1	0	0
Copper	ppm	ASTM D5185m	>50	<1	3	0
Tin	ppm	ASTM D5185m	>10	<1	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		17	14	16
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		5	4	4
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		17	5	13
Calcium	ppm	ASTM D5185m		466	406	441
Phosphorus	ppm	ASTM D5185m		404	381	405
Zinc	ppm	ASTM D5185m		171	152	166
Sulfur	ppm	ASTM D5185m		16768	14380	16488
CONTAMINAN	ITS	method	limit/base	current	history1	history
Silicon	ppm	ASTM D5185m	>75	8	4	6
Sodium	ppm	ASTM D5185m		0	<1	<1
Potassium	ppm	ASTM D5185m	>20	1	0	0
VISUAL		method	limit/base	current	history1	history?
	scalar	method *Visual	limit/base	current <b>NONE</b>	history1 NONE	history: NONE
White Metal	scalar scalar					
White Metal Yellow Metal		*Visual	NONE	NONE	NONE	NONE
White Metal Yellow Metal Precipitate	scalar	*Visual	NONE NONE	NONE NONE	NONE NONE	NONE NONE
White Metal Yellow Metal Precipitate Silt	scalar scalar	*Visual *Visual *Visual	NONE NONE	NONE NONE NONE	NONE NONE	NONE NONE
White Metal Yellow Metal Precipitate Silt Debris	scalar scalar scalar	*Visual  *Visual  *Visual  *Visual	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt	scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual	NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual  *Visual  *Visual	NONE NONE NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NONE NORML





# **OIL ANALYSIS REPORT**






















Certificate 12367

Sample No.

Lab Number : 06189592 Unique Number : 11046344

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0115572

Received : 23 May 2024 **Tested** 

: 24 May 2024 Diagnosed

: 28 May 2024 - Sean Felton

Test Package : MOB 1 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**CHICAGO MACHINERY INC** 

3142 EAST LINCOLN LYNWOOD, IL US 60411-7728

Contact: Mike Korbelik mike@chicagomachineryinc.com

T: (708)758-2060