


OIL ANALYSIS REPORT

ELEVATOR DISTRIBUTION LEG DISTRIBUTION LEG

Component **Gearbox**

HYDROTEX Ultra-Kleen ISO 220 (9 GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0123404	PCA0123397	PCA0113070
Sample Date		Client Info		17 May 2024	25 Apr 2024	21 Mar 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	_S	method	limit/base	current	history1	history2
PQ		ASTM D8184		30	34	33
Iron	ppm	ASTM D5185m	>200	24	25	24
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		<1	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	0	0
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	1	0	<1
Tin	ppm	ASTM D5185m	>25	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		100	118	109
Barium	ppm	ASTM D5185m		0	2	<1
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		<1	<1	0
Calcium	ppm	ASTM D5185m		4	0	0
Phosphorus	ppm	ASTM D5185m		448	442	449
Zinc	ppm	ASTM D5185m		2	8	0
Sulfur	ppm	ASTM D5185m		9490	10519	11366
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	48	50	45
Sodium	ppm	ASTM D5185m		0	2	1
Potassium	ppm	ASTM D5185m	>20	2	0	0
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
A -1-I NI (AAA)	1/011/	AOTA DOO!		4.46	4 40	

1.10

1.19


Acid Number (AN)


mg KOH/g ASTM D8045


1.11



OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROP	EULIES	method		History i	riistory
Visc @ 40°C	cSt	ASTM D445	213	213	213

SAMPLE IMAGES

Color

Bottom









Certificate 12367

Laboratory

Sample No. Lab Number : 06192981 Unique Number : 11049733

Test Package : PLANT

: PCA0123404

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 May 2024 **Tested**

: 05 Jun 2024 Diagnosed : 05 Jun 2024 - Jonathan Hester **Ardent Mills - Stockton** 3939 Producers Dr Stockton, CA US 95206

Contact: Noel Garcia noel.garcia@ardentmills.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: