


OIL ANALYSIS REPORT

KEMP QUARRIES / KEMP STONE - FAIRLAND [69383] **OHT123**

Transmission (Auto)

PETRO CANADA PRODURO TO-4 SAE 30 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. (Customer Sample Comment: PM-2 changed fluid and filters)

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


Fluid Condition


The condition of the fluid is acceptable for the time in service.

(GAL)		Dec2021	May2022 Aug2022	Jun 2023 Oct2023 Jan 2024	May2024	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0109097	PCA0070629	PCA0084733
Sample Date		Client Info		22 May 2024	02 Jan 2024	02 Oct 2023
Machine Age	hrs	Client Info		38485	37987	37517
Oil Age	hrs	Client Info		38485	37987	37517
Oil Changed		Client Info		Changed	N/A	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	12	2	6
Chromium	ppm	ASTM D5185m	>5	0	0	3
Nickel	ppm	ASTM D5185m	>5	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>5	<1	0	0
Aluminum	ppm	ASTM D5185m	>50	2	<1	2
_ead	ppm	ASTM D5185m	>50	<1	0	0
Copper	ppm	ASTM D5185m	>225	4	10	158
Tin	ppm	ASTM D5185m	>10	<1	<1	<1
√anadium	ppm	ASTM D5185m	7.0	0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	0	<1	2
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	2	<1	2
Manganese	ppm	ASTM D5185m	9	<1	<1	0
Magnesium	ppm	ASTM D5185m	1	36	44	16
Calcium	ppm	ASTM D5185m	3131	1748	2660	3058
Phosphorus	ppm	ASTM D5185m	1194	707	952	840
Zinc	ppm	ASTM D5185m	1281	848	1154	1097
Sulfur	ppm	ASTM D5185m	3811	2796	3589	3855
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	8	5
Sodium	ppm	ASTM D5185m		1	<1	0
Potassium	ppm	ASTM D5185m	>20	1	<1	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	LIGHT	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
40:36) Rev: 1	oddiai	riodai			1120	Submitted By



OIL ANALYSIS REPORT









Certificate 12367

Sample No. Lab Number : 06193165 Unique Number : 11049917 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0109097

Received : 28 May 2024 **Tested** : 30 May 2024

Diagnosed : 30 May 2024 - Sean Felton

Kemp Quarries - Kemp Stone - Fairland

18350 S 590 Rd Fairland, OK US 74343

Contact: fairland@kempstone.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: