


OIL ANALYSIS REPORT

KEMP QUARRIES / RIVER VALLEY BACKBONE **OHT087**

Component **Hydraulic System**

MOBIL DELVAC 1300 SUPER15W40 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type.

SAMPLE INFORM	NATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0108617	PCA0069907	PCA0084886
Sample Date		Client Info		23 May 2024	28 Dec 2023	13 Oct 2023
Machine Age	hrs	Client Info		34560	33775	33094
Oil Age	hrs	Client Info		785	1200	600
Oil Changed		Client Info		Not Changd	Changed	Not Changd
Sample Status				ATTENTION	NORMAL	NORMAL
CONTAMINATI	ON	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS	3	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	2	5	3
Chromium	ppm	ASTM D5185m	>10	0	<1	<1
Nickel	ppm	ASTM D5185m	>10	1	2	1
Titanium	ppm	ASTM D5185m		0	<1	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>10	<1	2	2
Lead	ppm	ASTM D5185m	>10	<1	<1	<1
Copper	ppm	ASTM D5185m	>75	<1	1	1
Tin	ppm	ASTM D5185m	>10	<1	<1	0
Vanadium	ppm	ASTM D5185m	>10	0	0	0
Cadmium		ASTM D5185m		0	<1	<1
	ppm	AO INI DO IOOIII		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	1	0	0
Barium	ppm	ASTM D5185m	0	0	0	9
Molybdenum	ppm	ASTM D5185m	0	1	2	2
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m	0	11	12	14
Calcium	ppm	ASTM D5185m		<u> </u>	92	88
Phosphorus	ppm	ASTM D5185m		363	380	369
Zinc	ppm	ASTM D5185m		460	443	454
Sulfur	ppm	ASTM D5185m		1092	1038	928
CONTAMINAN [*]	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	2	3	3
Sodium	ppm	ASTM D5185m		1	0	0
Potassium	ppm	ASTM D5185m	>20	2	<1	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
				_		
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water Free Water	scalar	*Visual	>0.1	NEG	NEG	NEG
	scalar	*Visual		NEG	NEG	NEG



OIL ANALYSIS REPORT









Sample No.

Lab Number : 06193183

: PCA0108617

Unique Number : 11049935

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 May 2024 **Tested**

: 30 May 2024 Diagnosed : 30 May 2024 - Sean Felton

5600 S Hwy 253 Huntington, AR US 72940 Contact:

Test Package : MOB 1 Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

backbone@rivervalleyquarries.com T:

Kemp Quarries - River Valley - Backbone

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: