


OIL ANALYSIS REPORT



KEMP QUARRIES / RIVER VALLEY BACKBONE OHT082

Rear Right Final Drive

MOBIL MOBILTRANS HD 50 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Woor

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.


SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0108992	PCA0086915	PCA0069703
Sample Date		Client Info		18 Jun 2024	10 Apr 2024	06 Nov 2023
Machine Age	hrs	Client Info		3576	3400	3045
Oil Age	hrs	Client Info		1237	1237	3045
Oil Changed	0	Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
·	ION	and the set	11			
CONTAMINAT Water	ION	method WC Method	limit/base	current	history1 NEG	history2 NEG
	<u> </u>					
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	15	12	34
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>5	<1	<1	<1
Titanium	ppm	ASTM D5185m	>15	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	<1	0	<1
Aluminum	ppm	ASTM D5185m	>75	2	2	2
Lead	ppm	ASTM D5185m	>10	1	<1	<1
Copper	ppm	ASTM D5185m	>75	2	1	6
Tin	ppm	ASTM D5185m	>8	0	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	<1	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		5	2	7
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		2	2	3
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		14	12	36
Calcium	ppm	ASTM D5185m		2425	2518	2147
Phosphorus	ppm	ASTM D5185m		721	695	720
Zinc	ppm	ASTM D5185m		827	861	877
Sulfur	ppm	ASTM D5185m		3824	3359	5662
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	12	16	13
Sodium	ppm	ASTM D5185m		2	0	0
Potassium	ppm	ASTM D5185m	>20	<1	2	2
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual	Z U.L	NEG	NEG	NEG
1 100 Water	Juaiai	visual		ITLU	IVLU	INLU



OIL ANALYSIS REPORT









Certificate 12367

Sample No. Lab Number : 06222907 Unique Number : 11101104

: PCA0108992

Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Jun 2024 **Tested** : 28 Jun 2024

Diagnosed : 30 Jun 2024 - Don Baldridge

5600 S Hwy 253 Huntington, AR US 72940

Contact: backbone@rivervalleyquarries.com

Kemp Quarries - River Valley - Backbone

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: KEMHUN [WUSCAR] 06222907 (Generated: 06/30/2024 09:46:38) Rev: 1

Submitted By:

T:

F: