


OIL ANALYSIS REPORT



Area (27KM1B) 413116

Transmission (Auto)

PETRO CANADA DuraDrive HD Synthetic 668 (--- QTS)



DIAGNOSIS

Recommendation

We suspect abnormal contamination may be due to sampling method. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.


Fluid Condition

The condition of the fluid is acceptable for the time in service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0122918	GFL0102459	GFL0102493
Sample Date		Client Info		25 Jun 2024	06 Jan 2024	29 Dec 2023
Machine Age	hrs	Client Info		3253	2292	2247
Oil Age	hrs	Client Info		3144	0	0
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ABNORMAL	ABNORMAL	NORMAL
CONTAMINATI	ON	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS	3	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>220	50	37	43
Chromium	ppm	ASTM D5185m		<1	0	0
Nickel	ppm	ASTM D5185m	>5	<1	0	0
Titanium	ppm	ASTM D5185m		<1	<1	0
Silver	ppm	ASTM D5185m	>5	<1	0	0
Aluminum	ppm	ASTM D5185m		25	21	19
Lead	ppm	ASTM D5185m	>95	7	2	3
Copper	ppm	ASTM D5185m	>60	27	17	18
Tin	ppm	ASTM D5185m	>10	5	3	4
Vanadium	ppm	ASTM D5185m	710	<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		60	53	52
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		2	<1	0
Manganese	ppm	ASTM D5185m		2	2	2
Magnesium	ppm	ASTM D5185m		2	2	0
Calcium	ppm	ASTM D5185m		120	131	122
Phosphorus	ppm	ASTM D5185m		188	200	209
Zinc	ppm	ASTM D5185m		8	8	0
Sulfur	ppm	ASTM D5185m		1559	1722	1866
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	7	12	5
Sodium	ppm	ASTM D5185m		5	5	6
Potassium	ppm	ASTM D5185m	>20	5	1	3
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
		*\ /! 1	NONE	▲ MODER	▲ MODER	NONE
Silt	scalar	*Visual	INOINE	- MODER	IVIODEIT	ITOITE
Silt Debris	scalar scalar	*Visual	NONE	NONE	NONE	NONE
				-		
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Debris Sand/Dirt	scalar scalar	*Visual	NONE NONE	NONE NONE	NONE NONE	NONE NONE
Debris Sand/Dirt Appearance	scalar scalar scalar	*Visual *Visual *Visual	NONE NONE NORML	NONE NONE NORML	NONE NONE NORML	NONE NONE NORML




OIL ANALYSIS REPORT





FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	34	32.23	32.3	32.0
SAMPLE IMAG	GES	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
GRAPHS						

Ferrous Alloys



Non-ferrous Metals









Certificate 12367

Laboratory

Sample No. : GFL0122918 Lab Number : 06225434

Unique Number : 11103631 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 01 Jul 2024

Tested : 08 Jul 2024 Diagnosed : 08 Jul 2024 - Jonathan Hester

7801 East Truman Road Kansas City, MO US 64126

GFL Environmental - 836 - Kansas City Hauling

Contact: Loyce Stewart loyce.stewart@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: