


OIL ANALYSIS REPORT



NORMAL



Machine Id SPC2

Front Left Final Drive

PETRO CANADA TRAXON 80W90 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

•)		Marco	, Aprilor 1	may.or.	1100	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0123734	PCA0123808	PCA0118443
Sample Date		Client Info		26 Jun 2024	13 May 2024	08 Apr 2024
Machine Age	hrs	Client Info		10450	9562	8864
Oil Age	hrs	Client Info		500	0	0
Oil Changed		Client Info		Not Changd	Not Changd	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	40	9	18
Chromium	ppm	ASTM D5185m	>10	0	<1	0
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>25	<1	1	0
Lead	ppm	ASTM D5185m	>25	0	<1	0
Copper	ppm	ASTM D5185m	>50	0	<1	<1
Tin	ppm	ASTM D5185m	>10	0	<1	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	243	260	320	299
Barium	ppm	ASTM D5185m	1	0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m	2	1	1	1
Calcium	ppm	ASTM D5185m	6	11	<1	81
Phosphorus	ppm	ASTM D5185m	987	1049	1096	1048
Zinc	ppm	ASTM D5185m	1	0	<1	16
Sulfur	ppm	ASTM D5185m	21530	23018	21271	23253
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	9	8	0
Sodium	ppm	ASTM D5185m		3	<1	2
Potassium	ppm	ASTM D5185m	>20	<1	1	2
FLUID DEGRA	OATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	1.9	1.81	1.73	1.75



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	141.0	140	140	139
SAMPLE IMAC	GES	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
GRAPHS Iron (ppm)				Lead (ppm)		
Severe			15	Severe		
Abnormal			E 10	_		
0				Abnormal	I I I D	
Mar1/24		May13/24	Jun26/24	Mar1/24	Apr8/24	
Aluminum (ppm)		2		Chromium (p		
Severe		7		Severe		
Severe			<u>ا</u>	Abnormal		
Abnormal				0		
Mar1/24		May13/24	Jun26/24	Mar1/24	Apr8/24	
Copper (ppm)		×	⋾	Silicon (ppm)	Σ	
Severe			30	OT		
Abnormal			£ 20	0 + Abnormal		
24		724		0	74	
Mar1/24 Apr8/24		May13/24	Jun26/24	Mar1/24	Apr8/24	
Viscosity @ 40°C			(B/HC	Acid Number		
			Number (mg KOH/g)			
Abnormal			III per			
Abnormal			in a			





Certificate 12367

Laboratory Sample No.

: PCA0123734 Lab Number : 06226418

Test Package : MOB 2

100

Unique Number : 11109911

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 02 Jul 2024

Tested : 03 Jul 2024 : 03 Jul 2024 - Wes Davis Diagnosed

1500 COMMERCIAL AVE MINGO JUNCTION, OH US 43938

SCRAP METAL SERVICES (SMS Mill Services LLC)

Contact: FRANK NALLY fnally@scrapmetalservices.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: