


OIL ANALYSIS REPORT

1002-ELEVATOR-TRANSFER HOUSE-BASEMENT 24531-CONV BELT SOUTH BASEMENT E-054

Gearbox

HYDROTEX Ultra-Kleen ISO 220 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Jul2024		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0115164		
Sample Date		Client Info		10 Jul 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	8		
Chromium	ppm	ASTM D5185m	>15	1		
Nickel	ppm	ASTM D5185m	>15	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		95		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		13		
Phosphorus	ppm	ASTM D5185m		505		
Zinc	ppm	ASTM D5185m		22		
Sulfur	ppm	ASTM D5185m		11399		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.79		




OIL ANALYSIS REPORT







SAMPLE IMAGES	metnoa	ilmit/base	current	nistory i	nistory2
Color				no image	no image
Bottom				no image	no image

GRAPHS













Certificate 12367

Laboratory Sample No. **Lab Number** : 06232376 Unique Number : 11115869

: PCA0115164

Test Package : PLANT

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 Jul 2024 **Tested** : 11 Jul 2024

Diagnosed

: 11 Jul 2024 - Wes Davis

Contact: Chad Bates Chad.Bates@Ardentmills.com T: (618)416-9155

Ardent Mills-Alton

145 W. Broadway

Alton, IL

US 62002

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) Contact/Location: Chad Bates - ARDALT

Report Id: ARDALT [WUSCAR] 06232376 (Generated: 07/11/2024 10:44:56) Rev: 1