

OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL

Area NAT CUTS [99061683] **LINE 2 CUBER**

Hydraulic System AW HYDRAULIC OIL ISO 46 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0123501	PCA0111812	PCA0111813
Sample Date		Client Info		24 Jun 2024	30 May 2024	28 May 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	Filtered
Sample Status				NORMAL	NORMAL	ABNORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METAL	method	limit/base	current	history1	history2	
Iron	ppm	ASTM D5185m	>20	2	3	4
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m		<1	0	0
Aluminum	ppm	ASTM D5185m	>20	4	2	2
Lead	ppm	ASTM D5185m	>20	1	1	1
Copper	ppm	ASTM D5185m	>20	10	7	<u> </u>
Tin	ppm	ASTM D5185m	>20	<1	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	0
Barium	ppm	ASTM D5185m	5	0	0	0
Molybdenum	ppm	ASTM D5185m	5	<1	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	25	<1	<1	<1
Calcium	ppm	ASTM D5185m	200	0	0	0
Phosphorus	ppm	ASTM D5185m	300	476	523	492
Zinc	ppm	ASTM D5185m	370	41	38	38
Sulfur	ppm	ASTM D5185m	2500	1174	1433	1332
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	3	3	3
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	<1	<1
FLUID CLEANI	LINESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	3123	561	A 37643
Particles >6µm		ASTM D7647	>1300	603	109	▲ 3992
Particles >14µm		ASTM D7647	>320	76	13	24
Particles >21µm		ASTM D7647	>80	10	3	2
Particles >38µm		ASTM D7647	>20	1	1	0
Particles >71µm		ASTM D7647	>4	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/15	19/16/13	16/14/11	A 22/19/12
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.57	0.17	0.19	0.20
4.97.47) Dov: 1			0-		Saniaa Managa	


Report Id: KRASPRMO [WUSCAR] 06240288 (Generated: 07/21/2024 14:37:47) Rev: 1


Contact/Location: Service Manager - KRASPRMO




OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	<u>.</u>		46	48.4	40 5	48.3
	cSt	ASTM D445	40	40.4	48.5	40.3
SAMPLE IMAG		method	limit/base	current	48.5 history1	46.3 history2



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 KraftHeinz - Springfield - Plant 8311 PCA Sample No. : PCA0123501 Received : 18 Jul 2024 2035 E BENNETT Lab Number : 06240288 Tested : 19 Jul 2024 SPRINGFIELD, MO Unique Number : 11129122 Diagnosed : 20 Jul 2024 - Don Baldridge US 65804 Test Package : IND 2 Contact: Service Manager Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369. T: * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

Report Id: KRASPRMO [WUSCAR] 06240288 (Generated: 07/21/2024 14:37:47) Rev: 1

Contact/Location: Service Manager - KRASPRMO