



CONSTRUCTION EQUIPMENT

499970-01 VOLVO EC360CL 140079 - BOGIE/CENTER LEFT FINAL DRIVE



Sample No: VCP076504
Oil Type: {unknown}
Job No: 499970-01



STRONGCO INC. - BAIE COMEAU
2107 AVENUE DU LABRADOR
BAIE COMEAU, QC
CA G4Z 3B9
Contact: Denis Lejeune
dlejeune@strongco.com
T: (418)589-4141
F:



SAMPLE INFORMATION

Sample Number	VCP076504	---	---	---
Sample Date	02 Oct 2009	---	---	---
Machine Hours	89	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	163	---	---	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	11	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	1	---	---	---



WEAR METALS

Iron	ppm	125	---	---	---
Copper	ppm	<1	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	2	---	---	---
Aluminum	ppm	1	---	---	---
Chromium	ppm	2	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	3	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	13	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	24	---	---	---
Phosphorus	ppm	1116	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	0	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le composant. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO4593
Unique No: 2992668
Signed:
Report Date: 09 Oct 2009



CONSTRUCTION EQUIPMENT



GRAPHS

