## CONSTRUCTION EQUIPMENT 521239-01 VOLVOL150 61705 - REAR AXLE



| Sample No: | VCP093031 |
|------------|-----------|
| Oil Type:  | {unknown} |
| Job No:    | 521239-01 |

VOLVO

#### SAMPLE INFORMATION VCP093031 Sample Number Sample Date 25 May 2010 Machine Hours 58114 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 48.1 CONTAMINATION Silicon ppm 10 Sodium **4** ppm Potassium 10 ppm WEAR METALS Iron ppm 22 Copper ppm ■ <1 Lead ppm 0 🔲 Tin ppm **||** <1 Aluminum ppm **||** <1 Chromium ppm ■<1 Molybdenum ppm 1 Nickel 0 ppm Titanium <1 ppm Silver 0 ppm Manganese <1 ppm Vanadium ppm 0 **ADDITIVES** 2464 Calcium ppm Magnesium 9 ppm 1170 Zinc ppm Phosphorus 1010 ppm



#### STRONGCO INC

1575 RUE BERSIMIS CHICOUTIMI, QC CA G7K 1G9 Contact: Dany Levesque dlevesque@strongco.com T: (418)690-1724 F: (418)690-5002

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

| Depot:       | VOLVO0230    |
|--------------|--------------|
| Unique No:   | 3119324      |
| Signed:      | Kevin Marson |
| Report Date: | 31 May 2010  |

2

2

ppm

ppm

Barium

Boron

# **CONSTRUCTION EQUIPMENT**



GRAPHS

#### Ferrous Alloys

VOLVO

