



CONSTRUCTION EQUIPMENT

521239-01 VOLVO L150 61705 - FRONT AXLE



Sample No: VCP093030
Oil Type: {unknown}
Job No: 521239-01



SAMPLE INFORMATION

Sample Number	VCP093030	---	---	---
Sample Date	25 May 2010	---	---	---
Machine Hours	58114	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO INC

1575 RUE BERSIMIS
 CHICOUTIMI, QC
 CA G7K 1G9

Contact: Dany Levesque
 dlevesque@strongco.com
 T: (418)690-1724
 F: (418)690-5002



OIL CONDITION

Visc @ 40°C	cSt	43.3	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	12	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	4	---	---	---



WEAR METALS

Iron	ppm	30	---	---	---
Copper	ppm	<1	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	2	---	---	---
Chromium	ppm	<1	---	---	---
Molybdenum	ppm	3	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	2970	---	---	---
Magnesium	ppm	9	---	---	---
Zinc	ppm	1319	---	---	---
Phosphorus	ppm	1118	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	41	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0230
Unique No: 3119327
Signed: Kevin Marson
Report Date: 31 May 2010




CONSTRUCTION EQUIPMENT




GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C

