CONSTRUCTION EQUIPMENT 636308-01 VOLVO 6157 - TRANSMISSION (AUTO)



Sample No: VCE187703 Oil Type: VOLVO AU

VOLVO

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No:

Silver

Manganese

Vanadium

01

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

636308-01

SAMPLE INFORMATION VCE187703 Sample Number VCP123024 Sample Date 19 Jun 2013 09 Dec 2011 Machine Hours 8157 5932 Oil Hours 0 0 Oil Changed Changed Changed NORMAL NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 27.9 23.2 CONTAMINATION Water % NEG NEG 9 Silicon 4 ppm Sodium 6 🔲 9 ppm Potassium ppm 0 2 WEAR METALS Iron ppm 31 60 Copper ppm 5 10 Lead ppm **||** <1 < 1 Tin ppm 0 0 Aluminum ■<1 <1 ppm Chromium **||** <1 <1 ppm Molybdenum ppm 0 < 1 Nickel 0 □ < 1 ppm Titanium ppm 0 0

0

0

231

3

52

420

0

96

1



RIDEAU BULK TERMINALS

6960 4TH LINE ROAD,, OLD HWY 16 KEMPTVILLE, ON CA KOG 1J0 Contact: Mark Yelle myelle@rideaubulk.com T: (613)489-1440 F: (613)489-1428

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.

Depot:	RIDNOR
Unique No:	3739241
Signed:	Wes Davis
Report Date:	21 Jun 2013
Contact/Location: Mark Yelle - RIDNOR	

0

<1

0

151

3

24

279

<1

102

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm


ADDITIVES

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: RIDNOR [WCAMIS] 01845941 (Generated: 06/26/2024 10:57:01) Rev: 1

Contact/Location: Mark Yelle - RIDNOR