



# CONSTRUCTION EQUIPMENT

## VOLVO A30G 742128 - TRANSMISSION (AUTO)



**Sample No:** PP387380  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:**



**STRONGCO EQUIPMENT-EDMONTON**  
 25616 117 Ave NW  
 Acheson, AB  
 CA T7X 6C2  
 Contact: Jonathan Morton  
 jmorton@strongco.com  
 T: (780)464-1909  
 F: (780)464-0434



### SAMPLE INFORMATION

Sample Number	PP387380	---	---	---
Sample Date	06 Jun 2019	---	---	---
Machine Hours	1002	---	---	---
Oil Hours	1002	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



### OIL CONDITION

Visc @ 40°C	cSt	█ 30.1	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 16	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ 6	---	---	---



### WEAR METALS

Iron	ppm	█ 39	---	---	---
Copper	ppm	█ 14	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 5	---	---	---
Aluminum	ppm	█ 25	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 156	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 11	---	---	---
Phosphorus	ppm	█ 268	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 76	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO3908  
**Unique No:** 4889094  
**Signed:** Wes Davis  
**Report Date:** 26 Jun 2019



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

