



CONSTRUCTION EQUIPMENT

JOHNSON&HERBERT VOLVO A30G 742211 - REAR AXLE



Sample No: PP396738
Oil Type: VOLVO
Job No: JOHNSON&HERBERT



SAMPLE INFORMATION

Sample Number	PP396738	---	---	---
Sample Date	07 Jun 2019	---	---	---
Machine Hours	1016	---	---	---
Oil Hours	1016	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW
Acheson, AB
CA TX 6C2

Contact: Jonathan Morton
jmorton@strongco.com
T: (780)464-1909
F: (780)464-0434



OIL CONDITION

Visc @ 40°C	cSt	52.7	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	<1	---	---	---
Sodium	ppm	3	---	---	---
Potassium	ppm	4	---	---	---



WEAR METALS

Iron	ppm	81	---	---	---
Copper	ppm	2	---	---	---
Lead	ppm	<1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	0	---	---	---
Chromium	ppm	1	---	---	---
Molybdenum	ppm	1	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	12	---	---	---
Magnesium	ppm	<1	---	---	---
Zinc	ppm	6	---	---	---
Phosphorus	ppm	2532	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	262	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 75W80 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot: VOLVO3908
Unique No: 4889106
Signed: Kevin Marson
Report Date: 27 Jun 2019



CONSTRUCTION EQUIPMENT



GRAPHS

