



# CONSTRUCTION EQUIPMENT

## VOLVO A30D 14069 - TRANSMISSION (AUTO)



**Sample No:** VCP222695

**Oil Type:** DEXRON III

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP222695	---	---	---
Sample Date	26 Jun 2019	---	---	---
Machine Hours	29105	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

### STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW

Acheson, AB

CA T7X 6C2

Contact: Jason Sweet

jsweet@strongco.com

T: Phone

F: (780)417-2615



### OIL CONDITION

Visc @ 40°C	cSt	■ 31.5	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	■ 7	---	---	---
Sodium	ppm	■ 7	---	---	---
Potassium	ppm	■ <1	---	---	---



### WEAR METALS

Iron	ppm	■ 18	---	---	---
Copper	ppm	■ 33	---	---	---
Lead	ppm	■ 2	---	---	---
Tin	ppm	■ 2	---	---	---
Aluminum	ppm	■ 4	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ <1	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	■ 133	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 8	---	---	---
Phosphorus	ppm	■ 419	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 191	---	---	---

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO3908

**Unique No:** 4889779

**Signed:** Wes Davis

**Report Date:** 28 Jun 2019



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

