



CONSTRUCTION EQUIPMENT

213910 VOLVO A25E 13189 - TRANSMISSION (AUTO)



Sample No: VCP243245

Oil Type: NOT GIVEN

Job No: 213910



SAMPLE INFORMATION

Sample Number	VCP243245	---	---	---
Sample Date	13 Sep 2019	---	---	---
Machine Hours	7593	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



STRONGCO INC

1575 RUE BERSIMIS

CHICOUTIMI, QC

CA G7K 1G9

Contact: Dany Levesque

dlevesque@strongco.com

T: (418)690-1724

F: (418)690-5002



OIL CONDITION

Visc @ 40°C	cSt	■ 37.2	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 13	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 1	---	---	---



WEAR METALS

Iron	ppm	■ 36	---	---	---
Copper	ppm	■ 312	---	---	---
Lead	ppm	■ 10	---	---	---
Tin	ppm	■ 9	---	---	---
Aluminum	ppm	■ 8	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	9	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	■ <1	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	782	---	---	---
Magnesium	ppm	39	---	---	---
Zinc	ppm	356	---	---	---
Phosphorus	ppm	455	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	96	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le le fluide. L'état de le fluide est acceptable pour la durée de service.

Depot: VOLVO0230

Unique No: 4929540

Signed: Kevin Marson

Report Date: 24 Sep 2019



CONSTRUCTION EQUIPMENT



GRAPHS

