



CONSTRUCTION EQUIPMENT

234823 VOLVO L180R 6636 - REAR AXLE



Sample No: VCP252125
Oil Type: TDH FLUID SAE 75W80
Job No: 234823



SAMPLE INFORMATION

Sample Number	VCP252125	---	---	---
Sample Date	02 Mar 2020	---	---	---
Machine Hours	21600	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

STRONGCO EQUIPMENT

5200 BOUL ST JOSEPH
 TROIS RIVIERE, QC
 CA G8Z 4L8
 Contact: Sebastien Rocheleau
 srocheleau@strongco.com
 T: (855)840-0828
 F: (819)840-0829



OIL CONDITION

Visc @ 40°C	cSt	█ 49.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 1	---	---	---



WEAR METALS

Iron	ppm	█ 8	---	---	---
Copper	ppm	█ < 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ < 1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ < 1	---	---	---
Titanium	ppm	< 1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ < 1	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 3101	---	---	---
Magnesium	ppm	█ 30	---	---	---
Zinc	ppm	█ 1223	---	---	---
Phosphorus	ppm	█ 1013	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 98	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) TDH FLUID SAE 75W80. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: STR520TRO
Unique No: 5017179
Signed: Wes Davis
Report Date: 06 Mar 2020



CONSTRUCTION EQUIPMENT



GRAPHS

