



# CONSTRUCTION EQUIPMENT

234827 VOLVO L180E 6638 - REAR AXLE



**Sample No:** VCP240971  
**Oil Type:** TDH FLUID SAE 75W80  
**Job No:** 234827



## SAMPLE INFORMATION

Sample Number	VCP240971	---	---	---
Sample Date	02 Mar 2020	---	---	---
Machine Hours	8809	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

## STRONGCO EQUIPMENT

5200 BOUL ST JOSEPH  
TROIS RIVIERE, QC  
CA G8Z 4L8  
Contact: Sebastien Rocheleau  
srocheleau@strongco.com  
T: (855)840-0828  
F: (819)840-0829



## OIL CONDITION

Visc @ 40°C	cSt	█ 48.2	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 1	---	---	---



## WEAR METALS

Iron	ppm	█ 7	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 3090	---	---	---
Magnesium	ppm	█ 30	---	---	---
Zinc	ppm	█ 1231	---	---	---
Phosphorus	ppm	█ 1026	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	98	---	---	---

## Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) TDH FLUID SAE 75W80. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

**Depot:** STR520TRO  
**Unique No:** 5017181  
**Signed:** Wes Davis  
**Report Date:** 06 Mar 2020



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

