



CONSTRUCTION EQUIPMENT

238576 VOLVO A40G 340219 - DROP BOX



Sample No: VCP263017

Oil Type: NOT GIVEN

Job No: 238576



SAMPLE INFORMATION

Sample Number	VCP263017	VCP238811	---	---
Sample Date	27 Mar 2020	08 Feb 2019	---	---
Machine Hours	7370	7339	---	---
Oil Hours	0	0	---	---
Oil Changed	Not Changed	Changed	---	---
Sample Status	NORMAL	ABNORMAL	---	---



STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
St-Augustin-de-Desmaures, QC
CA G3A 2K2

Contact: Michel Lepage
mlepage@strongco.com
T: (418)870-1700
F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	54.2	60.04	---	---
-------------	-----	-------------	-------	-----	-----



CONTAMINATION

Silicon	ppm	6	54	---	---
Sodium	ppm	1	4	---	---
Potassium	ppm	<1	6	---	---



WEAR METALS

Iron	ppm	50	519	---	---
Copper	ppm	<1	2	---	---
Lead	ppm	<1	3	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	7	77	---	---
Chromium	ppm	<1	6	---	---
Molybdenum	ppm	<1	7	---	---
Nickel	ppm	<1	1	---	---
Titanium	ppm	<1	<1	---	---
Silver	ppm	<1	0	---	---
Manganese	ppm	1	10	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	14	90	---	---
Magnesium	ppm	4	36	---	---
Zinc	ppm	19	138	---	---
Phosphorus	ppm	2323	1290	---	---
Barium	ppm	0	0	---	---
Boron	ppm	249	86	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Veuillez préciser la marque, le type et la viscosité de l'huile lors de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5030659
Signed: Kevin Marson
Report Date: 02 Apr 2020



CONSTRUCTION EQUIPMENT



GRAPHS

