

CONSTRUCTION EQUIPMENT 8000255020 VOLVO L110F 70735 - FRONT AXLE



Sample No: VCP252278

Oil Type: TRANSAXLE OIL SAE 75W80

Job No: 8000255020

VOLVO				
SAMPLE	INFORMATION			
Sample Number		VCP252278	 	
Sample Date		28 Aug 2020	 	
Machine Hours		6747	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	43.5	 	
Vise g 10 c	231	.5.5		
VOLVO	411.5.5.0.1			
CONTAN	MINATION			
Silicon	ppm	10	 	
Sodium	ppm	■<1	 	
Potassium	ppm	■<1	 	
WEAR N	METALS			
Iron	ppm	■7	 	
Copper	ppm	■ <1	 	
Lead	ppm	0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■ <1	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■ <1	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIV	JES			
Calcium	ppm	■4077	 	
Magnesium	ppm	12	 	
Zinc	ppm	1662	 	
Phosphorus	ppm	■1308	 	
Barium	ppm	■ <1	 	
Boron	ppm	113		



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jonathan Morton jmorton@strongco.com T: (780)464-1909 F: (780)464-0434

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TRANSAXLE OIL SAE 75W80. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3908Unique No:5097544Signed:Wes DavisReport Date:03 Sep 2020



CONSTRUCTION EQUIPMENT





GRAPHS

