



CONSTRUCTION EQUIPMENT

280258 VOLVO A35C 4656 - TRANSMISSION (AUTO)



Sample No: VCP280646

Oil Type: DEXRON III

Job No: 280258



SAMPLE INFORMATION

Sample Number	VCP280646	---	---	---
Sample Date	31 Mar 2021	---	---	---
Machine Hours	12399	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



STRONGCO EQUIPMENT INC (STE- FOY)

175, rue de Rotterdam
St-Augustin-de-Desmaures, QC
CA G3A 2K2

Contact: Michel Lepage
mlepage@strongco.com
T: (418)870-1700
F: (418)870-1701



OIL CONDITION

Visc @ 40°C	cSt	█ 25.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 1	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 20	---	---	---
Copper	ppm	█ 28	---	---	---
Lead	ppm	█ 4	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 5	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 129	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 25	---	---	---
Phosphorus	ppm	█ 223	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 99	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du (GENERIC) DEXRON III. Veuillez confirmer. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans le le fluide. L'état de le fluide est acceptable pour la durée de service.

Depot: VOLVO0228
Unique No: 5200971
Signed: Wes Davis
Report Date: 06 Apr 2021



CONSTRUCTION EQUIPMENT



GRAPHS

